

MEDICAL

TECHNICAL SERVICE BULLETIN #10

Product: Fabius GS

Date: March 29, 2004

Re: Software Release – 2.06

Reference Doc: Product Bulletin #164, SP00297

Reason/Rational: Enhancement – See Product Bulletin #164 for details

Solution/Procedure: Perform Software 2.06 upgrade on all Fabius GS units currently

containing 2.n version. Complete the Return Form (attached) and

return to DMI/DS within 7 days of account completion.

Devices affected: All Fabius GS containing 2.n only.

Timing/When: At customer request, next service or Periodic Manufacturer's

Service

Additional Info: Fabius GS units containing software 2.n shall be updated to 2.06

by ordering Software Kit – 4118735

Note Do not install software 2.06 on Fabius GS units containing

1.3n. See TSB #9 for details.

Cost: Software upgrades to 2.06 are available to Fabius GS customers

at no charge.

Ordering Info/Parts: Contact your DMI Customer Service Representative to order the

software.

Distribution: DrägerService N.A. & all Authorized Service Organizations.

DrägerService 3122 Commerce Drive Telford, PA 18969 Tel: (215) 721-5402 (800) 543-5047 Fax: (215) 723-5935

Web: www.draegermedical.com

DrägerService is a division of Draeger Medical, Inc.



Product: Fabius GS

Return Form - Software 2.06 Upgrade

Distributor:	Customer:		
Country:	Address: City:		
	Machine S/N	Machine S/N	Machine S/N
			
			
Fax To:		Date of Update	
DrägerService		Signature (TSR)	

Name (Print) ____

DrägerService 3122 Commerce Drive Telford, PA 18969 Tel: (215) 721-5402 (800) 543-5047

Fax: (215) 723-5935

Web: www.draegermedical.com

Attn: Al Myers

DrägerService is a division of Draeger Medical, Inc.